Levelling

What is Levelling?

- Levelling is the process by which differences in height between two or more points can be determined.
- Measuring the height
- Measuring and calculating the height of a point relative to another point
- Height differences for 2+ points above datum (geoid).
 Determination of elevations with a surveying instrument

Levelling Staff



Basic Definitions

- <u>Vertical Line</u> is a line parallel to the direction of gravity
- Level Surface is a surface of constant elevation, that is perpendicular to the plumb bob line (vertical line) at every point
- <u>Level line</u> is a curved line in a level surface all points are of equal elevation
- <u>Horizontal line</u> is a straight line tangent to a level line at one point
- Horizontal plane is surface tangent to level surface at one point
- <u>Geoid</u> is the datum for all the vertical measurements and it is an equipotential surface perpendicular to vertical direction at each point on it. It can be realized approximately in nature by determining the mean sea level.
- Mean sea level, is defined as the position the sea or ocean would take if all tides and currents were eliminated and determined by averaging the hourly elevations of the sea over a long period of time, usually 19 years .

Basic Definitions

<u>Vertical datum</u> is basis of all elevations in levelling work and mostly defined by mean sea level.

Elevation of a point is the vertical distance above or below a reference level surface

Reduced level (RL): Height of a point above the particular datum used

Bench mark (BM) is Point with previously determined RL with respect to national vertical datum, and it is often constructed as permanent markers. Temporary bench mark (TBM) is a point referenced to arbitrary datum









Optical Levels

Automatic Level





Setting up the Tripod



•Position the tripod legs roughly over the place with the head of the tripod of the tripod roughly level.

•On soft ground, push the legs in firmly to stabilize the tripod.

Attaching the Level

Screw the level and tribrach on.

The level should be shaded from direct sunlight if possible.

The footscrews should be evenly set in the middle of their ranges so that the instrument is also roughly level.

Circular Bubble



















Move instrument to new positionLevel staff stays on B

The instrument has changed its position about point B

Point B is known as a Change Poir(CP)

2nd instrument position starts with BS to B



and finishes with FS to C



RLA is known

HPC = RLA + BSRLB = HPC - FSNow the RLB is knownSo we can repeat the process

RLB + BS RLC = HPC - FS

Generally : HPC = Known RL + Back Sight HPC = HPC - Fore Sight